

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW70284 REPORT No. B15-25317

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 29-Sep-15

DATE REPORTED: 02-Oct-15
SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter		E coli	Heterotrophic Plate Count	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			29-Sep-15/K	29-Sep-15/K	29-Sep-15/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr.	B15-25317-1	29-Sep-15	0	0	< 10	

R.L. = Reporting LImit

Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill

Uncertainty Values available upon request

Derek Winterton for Richard Lecompte Lab Supervisor