

C.O.C.: DW61832

REPORT No. B15-28770

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 03-Nov-15

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 06-Nov-15

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

Client I.D.	70 Main St. W Lyn	Pumphouse		
Sample I.D.	B15-28770-1	B15-28770-2		
Date Collected	03-Nov-15	03-Nov-15		

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Nitrite (N)	mg/L	0.1	SM4110C	04-Nov-15/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	04-Nov-15/O		< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	04-Nov-15/O		< 0.1		
Chloroform	µg/L	0.3	EPA 8260	04-Nov-15/O	< 0.3			
Bromodichloromethane	µg/L	0.1	EPA 8260	04-Nov-15/O	< 0.1			
Dibromochloromethane	µg/L	0.1	EPA 8260	04-Nov-15/O	0.8			
Bromoform	µg/L	0.1	EPA 8260	04-Nov-15/O	< 0.1			
Total Trihalomethanes	µg/L	0.3	EPA 8260	04-Nov-15/O	0.8			



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit
 Site Analyzed: K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill
 Uncertainty Values available upon request

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.