

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW62191 REPORT No. B16-00526

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 07-Jan-16

DATE REPORTED: 11-Jan-16

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter		E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
	Units		cfu/100mL			
	R.L.	R.L.				
	Reference Method  Date Analyzed/Site		MOE E3407			
			07-Jan-16/K	07-Jan-16/K	07-Jan-16/K	
Client I.D.	Sample I.D.	Date Collected				·
70 Main St W	B16-00526-1	07-Jan-16	0	0	30	

Derek Winterton for Richard Lecompte Lab Supervisor