

C.O.C.: DW60874

REPORT No. B16-03159

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 08-Feb-16

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 10-Feb-16

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19A Buffalo Dr			
Sample I.D.	B16-03159-1			
Date Collected	08-Feb-16			

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Chloroform	µg/L	0.3	EPA 8260	09-Feb-16/O	0.9			
Bromodichloromethane	µg/L	0.1	EPA 8260	09-Feb-16/O	< 0.1			
Dibromochloromethane	µg/L	0.1	EPA 8260	09-Feb-16/O	< 0.1			
Bromoform	µg/L	0.1	EPA 8260	09-Feb-16/O	< 0.1			
Total Trihalomethanes	µg/L	0.3	EPA 8260	09-Feb-16/O	0.9			



Richard Lecompte
 Lab Supervisor

R.L. = Reporting Limit
 Test methods may be modified from specified reference method unless indicated by an *
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.