

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW61422 REPORT No. B16-06285

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE DECENTED 45 M

DATE RECEIVED: 15-Mar-16

DATE REPORTED: 17-Mar-16

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter Units R.L.		E coli cfu/100mL	Heterotrophic Plate Count cfu/mL 10	
	Units					
	R.L.					
	Reference Method Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			15-Mar-16/K	15-Mar-16/K	15-Mar-16/K	
Client I.D.	Sample I.D.	Date Collected				·
19A Buffalo Dr	B16-06285-1	15-Mar-16	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Derek Winterton for Richard Lecompte Lab Supervisor