

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW61014

REPORT No. B16-07338

eport To: Caduceon Environmental Laboratories			
Property Management Inc 285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1		
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001		
Attention: Isaac Berman	Fax: 613-544-2770		
DATE RECEIVED: 28-Mar-16	JOB/PROJECT NO.: HMR Estates Pump House		
DATE REPORTED: 30-Mar-16	P.O. NUMBER:		
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768		

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			28-Mar-16/K	28-Mar-16/K	28-Mar-16/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr.	B16-07338-1	28-Mar-16	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Derek Winterton for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.