

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW61020 REPORT No. B16-08720

Report To:

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 11-Apr-16

DATE REPORTED: 13-Apr-16

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter  Units R.L.  Reference Method Date Analyzed/Site		Total Coliform cfu/100mL 1 MOE E3407	E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
			11-Apr-16/K	11-Apr-16/K	11-Apr-16/K	
Client I.D.	Sample I.D.	Date Collected				·
78 Main St. W	B16-08720-1	11-Apr-16	0	0	10	
Pumphouse	B16-08720-2	11-Apr-16	0	0		

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Derek Winterton for Richard Lecompte Lab Supervisor