

C.O.C.: Dw61202

REPORT No. B16-11169

Report To:

Property Management Inc
323 Dundas Street East, Unit 3,
Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 02-May-16

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse


DATE REPORTED: 05-May-16

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

			Client I.D.	#24	Pumphouse		
			Sample I.D.	B16-11169-1	B16-11169-2		
			Date Collected	02-May-16	02-May-16		
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	03-May-16/K	0		
E coli	cfu/100mL	1	MOE E3407	03-May-16/K	0		
Nitrite (N)	mg/L	0.1	SM4110C	03-May-16/O		< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	03-May-16/O		3.5	
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	03-May-16/O		3.5	



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.