

C.O.C.: DW61203

REPORT No. B16-11181

Report To:

Property Management Inc
323 Dundas Street East, Unit 3,
Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 02-May-16

JOB/PROJECT NO.: HMR Estates Pump House


DATE REPORTED: 04-May-16

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

			Client I.D.	19A Buffalo Dr			
			Sample I.D.	B16-11181-1			
			Date Collected	02-May-16			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	0.3	EPA 8260	03-May-16/O	< 0.3		
Bromodichloromethane	µg/L	0.1	EPA 8260	03-May-16/O	< 0.1		
Dibromochloromethane	µg/L	0.1	EPA 8260	03-May-16/O	< 0.1		
Bromoform	µg/L	0.1	EPA 8260	03-May-16/O	< 0.1		
Total Trihalomethanes	µg/L	0.3	EPA 8260	03-May-16/O	< 0.3		



R.L. = Reporting Limit

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.