

C.O.C.: DW77581

REPORT No. B16-22581

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

DATE RECEIVED: 02-Aug-16

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 04-Aug-16

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

Client I.D.	70 main St.W			
Sample I.D.	B16-22581-1			
Date Collected	02-Aug-16			

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	0.3	EPA 8260	03-Aug-16/O	0.7		
Bromodichloromethane	µg/L	0.1	EPA 8260	03-Aug-16/O	2.7		
Dibromochloromethane	µg/L	0.1	EPA 8260	03-Aug-16/O	5.8		
Bromoform	µg/L	0.1	EPA 8260	03-Aug-16/O	3.8		
Total Trihalomethanes	µg/L	0.3	EPA 8260	03-Aug-16/O	13.1		



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.