

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW75842 REPORT No. B16-25759

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada Attention: Isaac Berman

DATE RECEIVED: 29-Aug-16

DATE REPORTED: 01-Sep-16

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1 Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units R.L. Reference Method		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	R.L.			1 MOE E3407	10 SM9215D	
	Reference Meth					
	Date Analyzed/Site		29-Aug-16/K	29-Aug-16/K	29-Aug-16/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St W	B16-25759-1	29-Aug-16	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Natasha Wright for Richard Lecompte Lab Supervisor