

CERTIFICATE OF ANALYSIS

Final Report

C.O.C.: DW70515 REPORT No. B16-27688

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 14-Sep-16

DATE REPORTED: 19-Sep-16

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

P.O. NUMBER:

WATERWORKS NO. 260019591

	Parameter Units R.L. Reference Method Date Analyzed/Site		Total Coliform	E coli		
			cfu/100mL	cfu/100mL		
			1	1		
			MOE E3407	MOE E3407		
			14-Sep-16/K	14-Sep-16/K		
Client I.D.	Sample I.D.	Date Collected			•	•
#24	B16-27688-1	14-Sep-16	0	0		
Pumphouse	B16-27688-2	14-Sep-16	0	0		

M.Duli

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Michelle Dubien Lab Manager