

C.O.C.: DW70805

REPORT No. B16-29230

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 28-Sep-16

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 03-Oct-16

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

| Parameter | Total Coliform | E coli | Heterotrophic Plate Count | | |
|--------------------|----------------|-------------|---------------------------|--|--|
| Units | cfu/100mL | cfu/100mL | cfu/mL | | |
| R.L. | 1 | 1 | 10 | | |
| Reference Method | MOE E3407 | MOE E3407 | SM9215D | | |
| Date Analyzed/Site | 28-Sep-16/K | 28-Sep-16/K | 28-Sep-16/K | | |

| Client I.D. | Sample I.D. | Date Collected | | | | |
|-------------|-------------|----------------|---|---|------|--|
| #24 | B16-29230-1 | 28-Sep-16 | 0 | 0 | < 10 | |



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.