

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW72619 REPORT No. B16-36123

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE DECENTED: OF De-

DATE RECEIVED: 05-Dec-16 DATE REPORTED: 08-Dec-16

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

| | Parameter Units R.L. Reference Method Date Analyzed/Site | | Total Coliform cfu/100mL 1 MOE E3407 | E coli cfu/100mL 1 MOE E3407 | Heterotrophic Plate Count cfu/mL 10 SM9215D | |
|--------------|---|-------------------|--|---------------------------------|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | 05-Dec-16/K | 05-Dec-16/K | 05-Dec-16/K | |
| Client I.D. | Sample I.D. | Date Collected | | • | | · |
| 70 Main St W | B16-36123-1 | 05-Dec-16 | 0 | 0 | 10 | |
| Pumphouse | B16-36123-2 | 05-Dec-16 | 0 | 0 | | |

R. Jeco pla

R.L. = Reporting Limit

Richard Lecompte Lab Supervisor

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill