

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW72773 REPORT No. B17-00309

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 04-Jan-17

DATE REPORTED: 09-Jan-17

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter		E coli	Heterotrophic Plate Count	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			04-Jan-17/K	04-Jan-17/K	04-Jan-17/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B17-00309-1	04-Jan-17	0	0	< 10	
Pumphouse	B17-00309-2	04-Jan-17	0	0		

M. Duci

R.L. = Reporting Limit

Michelle Dubien Lab Manager

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill