

**C.O.C.: DW72715**

**REPORT No. B17-03839**

**Report To:**

**Property Management Inc**  
323 Dundas Street East, Unit 3,  
Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
Kingston Ontario K7K 6Z1  
Tel: 613-544-2001  
Fax: 613-544-2770

DATE RECEIVED: 14-Feb-17

JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse

DATE REPORTED: 21-Feb-17

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019591

			Client I.D.	#26	Pumphouse-Raw	Pumphouse	
			Sample I.D.	B17-03839-1	B17-03839-2	B17-03839-3	
			Date Collected	14-Feb-17	14-Feb-17	14-Feb-17	
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	14-Feb-17/K	0	0	
E coli	cfu/100mL	1	MOE E3407	14-Feb-17/K	0	0	
Nitrite (N)	mg/L	0.1	SM4110C	15-Feb-17/O			< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	15-Feb-17/O			3.6
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	15-Feb-17/O			3.6



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \*

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte  
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.