

C.O.C.: DW72719

REPORT No. B17-03859

Report To:

Property Management Inc
323 Dundas Street East, Unit 3,
Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 14-Feb-17

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 17-Feb-17

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

			Client I.D.	70 Main St. W				
			Sample I.D.	B17-03859-1				
			Date Collected	14-Feb-17				
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Chloroform	µg/L	0.3	EPA 8260	16-Feb-17/O	0.3			
Bromodichloromethane	µg/L	0.1	EPA 8260	16-Feb-17/O	1.4			
Dibromochloromethane	µg/L	0.1	EPA 8260	16-Feb-17/O	3.5			
Bromoform	µg/L	0.1	EPA 8260	16-Feb-17/O	2.1			
Total Trihalomethanes	µg/L	0.3	EPA 8260	16-Feb-17/O	7.3			



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.