

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW80196 REPORT No. B17-07689

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 29-Mar-17

DATE REPORTED: 01-Apr-17

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter		E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL 1 MOE E3407			
			29-Mar-17/K	29-Mar-17/K	29-Mar-17/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B17-07689-1	29-Mar-17	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Derek Winterton for Richard Lecompte Lab Supervisor