

C.O.C.: DW76608

REPORT No. B17-11605

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

DATE RECEIVED: 03-May-17

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 08-May-17

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Client I.D.	Pumphouse			
Sample I.D.	B17-11605-1			
Date Collected	03-May-17			

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Nitrite (N)	mg/L	0.1	SM4110C	04-May-17/O	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	04-May-17/O	< 0.1		
Nitrate + Nitrite (N)	mg/L	0.1	SM4110C	04-May-17/O	< 0.1		



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Richard Lecompte
 Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.