

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW77145 REPORT No. B17-13859

**Report To:** 

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 24-May-17

DATE REPORTED: 27-May-17

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter		E coli  cfu/100mL  1  MOE E3407  24-May-17/K	Heterotrophic Plate Count cfu/mL 10 SM9215D 24-May-17/K	
	Units  R.L.  Reference Method  Date Analyzed/Site		cfu/100mL 1 MOE E3407 24-May-17/K			
Client I.D.	Sample I.D.	Date Collected				•
70 Main St W	B17-13859-1	24-May-17	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Derek Winterton for Richard Lecompte Lab Supervisor