

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW84695 REPORT No. B17-20207

Report To:

Property Management Inc 323 Dundas Street East, Unit 3,

Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 18-Jul-17
DATE REPORTED: 20-Jul-17

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter		E coli	Heterotrophic Plate Count	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			18-Jul-17/K	18-Jul-17/K	18-Jul-17/K	
Client I.D.	Sample I.D.	Date Collected				•
19A Buffalo Dr	B17-20207-1	18-Jul-17	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Evan Livermore

for Richard Lecompte Lab Supervisor