

## CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW83248 REPORT No. B17-30132

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 10-Oct-17

DATE REPORTED: 13-Oct-17

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter Units		Total Coliform cfu/100mL	E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
R.L.			1			
	Reference Method  Date Analyzed/Site		MOE E3407			
			11-Oct-17/K	11-Oct-17/K	11-Oct-17/K	
Client I.D.	Sample I.D.	Date Collected				·
70 Main St W	B17-30132-1	10-Oct-17	0	0	10	
Pumphouse-Raw	B17-30132-2	10-Oct-17	14	0		

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor