

C.O.C.: DW76629

REPORT No. B17-34078

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 08-Nov-17

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 13-Nov-17

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed	Client I.D.	#24	Pumphouse-Raw	Well #2-Raw	Pumphouse
					Sample I.D.	Date Collected			
Total Coliform	cfu/100mL	1	MOE E3407	08-Nov-17/K	B17-34078-1	07-Nov-17	0	0	2
E coli	cfu/100mL	1	MOE E3407	08-Nov-17/K	B17-34078-2	07-Nov-17	0	0	2
Heterotrophic Plate Count	cfu/mL	10	SM9215D	08-Nov-17/K	B17-34078-3	07-Nov-17	< 10		
Nitrite (N)	mg/L	0.1	SM4110C	09-Nov-17/O	B17-34078-4	07-Nov-17			0.1
Nitrate (N)	mg/L	0.1	SM4110C	09-Nov-17/O					< 0.1



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.