

CERTIFICATE OF ANALYSIS

Final Report

C.O.C.: DW87034 REPORT No. B18-11454

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 01-May-18

DATE REPORTED: 03-May-18

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

			Client I.D.		70 Main St W		
			Sample I.D.		B18-11454-1		
			Date Collected		01-May-18		
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	μg/L	0.3	EPA 8260	02-May-18/O	< 0.3		
Bromodichloromethane	μg/L	0.1	EPA 8260	02-May-18/O	0.4		
Dibromochloromethane	μg/L	0.1	EPA 8260	02-May-18/O	0.3		
Bromoform	μg/L	0.1	EPA 8260	02-May-18/O	0.3		
Total Trihalomethanes	μg/L	0.3	EPA 8260	02-May-18/O	1.0		

R. Jean Jos

R.L. = Reporting Limit

Richard Lecompte Lab Supervisor

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie