

C.O.C.: DW87032

REPORT No. B18-11456

Report To:

Property Management Inc
323 Dundas Street East, Unit 3,
Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
Kingston Ontario K7K 6Z1
Tel: 613-544-2001
Fax: 613-544-2770

DATE RECEIVED: 01-May-18

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 03-May-18

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

			Client I.D.	#24			
			Sample I.D.	B18-11456-1			
			Date Collected	01-May-18			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	0.3	EPA 8260	02-May-18/O	< 0.3		
Bromodichloromethane	µg/L	0.1	EPA 8260	02-May-18/O	< 0.1		
Dibromochloromethane	µg/L	0.1	EPA 8260	02-May-18/O	< 0.1		
Bromoform	µg/L	0.1	EPA 8260	02-May-18/O	< 0.1		
Total Trihalomethanes	µg/L	0.3	EPA 8260	02-May-18/O	< 0.3		

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.