

Client committed. Quality assured.

## CERTIFICATE OF ANALYSIS

## **Final Report-Microbiology**

## C.O.C.: DW89175

## **REPORT No. B18-18962**

Report To:	Caduceon Environmental Laboratories				
Property Management Inc	285 Dalton Ave				
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1				
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001				
Attention: Isaac Berman	Fax: 613-544-2770				
DATE RECEIVED: 03-Jul-18	JOB/PROJECT NO.: Lyn Valley Mobile Home				
DATE REPORTED: 06-Jul-18	P.O. NUMBER:				
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465				

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units		cfu/100mL	cfu/100mL	cfu/mL	
	R.L.		1	1	10	
	Reference Meth	od	MOE E3407	MOE E3407	SM9215D	
	Date Analyzed/Site		03-Jul-18/K	03-Jul-18/K	03-Jul-18/K	
Client I.D.	Sample I.D.	Date Collected				
70 Main St. W	B18-18962-1	02-Jul-18	0	0	< 10	
Pumphouse- RAW	B18-18962-2	02-Jul-18	16	1		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.