

**C.O.C.: DW83924**

**REPORT No. B18-23910**

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 13-Aug-18

JOB/PROJECT NO.: 227 Big Hill Rd - Pumphouse

DATE REPORTED: 16-Aug-18

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260019604

			Client I.D.	#24	Pumphouse		
			Sample I.D.	B18-23910-1	B18-23910-2		
			Date Collected	13-Aug-18	13-Aug-18		
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Total Coliform	cfu/100mL	1	MOE E3407	13-Aug-18/K	0		
E coli	cfu/100mL	1	MOE E3407	13-Aug-18/K	0		
Heterotrophic Plate Count	cfu/mL	10	SM9215D	13-Aug-18/K	10		
Fluoride	mg/L	0.1	SM4110C	14-Aug-18/O		0.5	
Nitrite (N)	mg/L	0.1	SM4110C	14-Aug-18/O		< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	14-Aug-18/O		< 0.1	



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \*

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Richard Lecompte

Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.