

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW83861

REPORT No. B18-27302

Report To:	Caduceon Environmental Laboratories
Property Management Inc	285 Dalton Ave
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001
Attention: Isaac Berman	Fax: 613-544-2770
DATE RECEIVED: 10-Sep-18	JOB/PROJECT NO.: HMR Estates Pump House
DATE REPORTED: 13-Sep-18	P.O. NUMBER:
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			10-Sep-18/K	10-Sep-18/K	10-Sep-18/K	
Client I.D.	Sample I.D.	Date Collected				
19 A Buffalo Dr.	B18-27302-1	10-Sep-18	0	0	< 10	
Pump House - Raw	B18-27302-2	10-Sep-18	0	0		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.