

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW83865 REPORT No. B18-30845

Report To:

Property Management Inc 323 Dundas Street East, Unit 3,

Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 09-Oct-18

DATE REPORTED: 11-Oct-18

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter  Units R.L. Reference Method Date Analyzed/Site		Total Coliform cfu/100mL 1 MOE E3407	E coli  cfu/100mL  1  MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D		
							İ
						·	
			09-Oct-18/K	09-Oct-18/K	09-Oct-18/K		
Client I.D.	Sample I.D.	Date Collected					·
19A Buffalo Dr	B18-30845-1	09-Oct-18	0	0	10		
Pumphouse-Raw	B18-30845-2	09-Oct-18	0	0			

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor