

## CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW83648 **REPORT No. B18-32834** 

**Report To:** 

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 23-Oct-18

DATE REPORTED: 26-Oct-18

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter Units		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
R.L.		1	1	10		
	Reference Method  Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D	
			24-Oct-18/K	24-Oct-18/K	24-Oct-18/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B18-32834-1	23-Oct-18	0	0	< 10	

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill, B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor