

C.O.C.: DW82307

REPORT No. B18-34349

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 06-Nov-18

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 09-Nov-18

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

Client I.D.	19A Buffalo Dr.	Pumphouse	Pumphouse-Raw	
Sample I.D.	B18-34349-1	B18-34349-2	B18-34349-3	
Date Collected	06-Nov-18	06-Nov-18	06-Nov-18	

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	06-Nov-18/K	0		0	
E coli	cfu/100mL	1	MOE E3407	06-Nov-18/K	0		0	
Heterotrophic Plate Count	cfu/mL	10	SM9215D	06-Nov-18/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	07-Nov-18/O		< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	07-Nov-18/O		< 0.1		



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods are modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.