

## CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: ---**REPORT No. B18-38684** 

**Report To:** 

**Caduceon Environmental Laboratories** 

JOB/PROJECT NO.: Lyn Valley Mobile Home

**Property Management Inc** 

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001

Fax: 613-544-2770

DATE RECEIVED: 19-Dec-18

SAMPLE MATRIX: Drinking Water

DATE REPORTED: 27-Dec-18

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter		E coli	Heterotrophic Plate Count		
	Units		cfu/100mL	cfu/100mL	cfu/mL		
	R.L.	R.L.		1	10		
	Reference Method  Date Analyzed/Site		MOE E3407	MOE E3407	SM9215D		
			19-Dec-18/K	19-Dec-18/K	19-Dec-18/K		
Client I.D.	Sample I.D.	Date Collected		•	•	•	•
70 Main St.W	B18-38684-1	19-Dec-18	0	0	< 10		

R.L. = Reporting Limit

Test methods are modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill, B-Barrie

Evan Livermore for Richard Lecompte Lab Supervisor