

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW099609 REPORT No. B19-08921

Report To:

Property Management Inc 323 Dundas Street East, Unit 3,

Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 08-Apr-19

DATE REPORTED: 11-Apr-19

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter Units R.L. Reference Method Date Analyzed/Site		Total Coliform cfu/100mL 1 MOE E3407	E coli cfu/100mL 1 MOE E3407	Heterotrophic Plate Count cfu/mL 10 SM9215D	
			08-Apr-19/K	08-Apr-19/K	08-Apr-19/K	
Client I.D.	Sample I.D.	Date Collected				·
19A Buffalo Dr	B19-08921-1	08-Apr-19	0	0	< 10	
Pumphouse-Raw	B19-08921-2	08-Apr-19	0	0		

0 00

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Senior Microbiology Analyst