

C.O.C.: DW099634

REPORT No. B19-13007

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 13-May-19

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 16-May-19

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

			Client I.D.	Pumphouse			
			Sample I.D.	B19-13007-1			
			Date Collected	13-May-19			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Nitrite (N)	mg/L	0.1	SM4110C	14-May-19/O	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	14-May-19/O	< 0.1		



Richard Lecompte
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.