

C.O.C.: DW099734

REPORT No. B20-04489

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 18-Feb-20

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 20-Feb-20

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed	Client I.D.	Sample I.D.	Date Collected
Nitrite (N)	mg/L	0.1	SM4110C	19-Feb-20/O	Pump House	B20-04489-1	17-Feb-20
Nitrate (N)	mg/L	0.1	SM4110C	19-Feb-20/O			

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie



Richard Lecompte
 Laboratory Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.