

C.O.C.: DW099733

REPORT No. B20-04508

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 18-Feb-20

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 26-Feb-20

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

			Client I.D.	19A Buffalo Dr			
			Sample I.D.	B20-04508-1			
			Date Collected	17-Feb-20			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Total Haloacetic Acids (HAA5)	µg/L	5.3	EPA 552.3	24-Feb-20	< 5.3		
Chloroacetic Acid	µg/L	4.7	EPA 552.3	24-Feb-20	< 4.7		
Bromoacetic Acid	µg/L	2.9	EPA 552.3	24-Feb-20	< 2.9		
Dichloroacetic Acid	µg/L	2.6	EPA 552.3	24-Feb-20	< 2.6		
Dibromoacetic Acid	µg/L	2.0	EPA 552.3	24-Feb-20	< 2.0		
Trichloroacetic Acid	µg/L	5.3	EPA 552.3	24-Feb-20	< 5.3		

Haloacetic acids subcontracted to SGS Lakefield.



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Richard Lecompte
 Laboratory Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.