

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW76638

REPORT No. B20-05090

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 24-Feb-20	JOB/PROJECT NO.: HMR Estates Pump House			
DATE REPORTED: 26-Feb-20	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768			

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units R.L.		cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
	Reference Meth	Reference Method		MOE E3407	SM9215D	
	Date Analyzed/Site		24-Feb-20/K	24-Feb-20/K	24-Feb-20/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B20-05090-1	24-Feb-20	0	0	< 10	

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Senior Microbiology Analyst

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.