

Client committed. Quality assured.

## CERTIFICATE OF ANALYSIS

**Final Report-Microbiology** 

## C.O.C.: DW098178

## REPORT No. B20-08008

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 25-Mar-20	JOB/PROJECT NO.: Lyn Valley Mobile Home			
DATE REPORTED: 27-Mar-20	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260023465			

	Parameter	Parameter Units R.L. Reference Method Date Analyzed/Site		E coli	Heterotrophic Plate Count		
	Units			cfu/100mL	cfu/mL		
	R.L.			1	10		
	Reference Meth			MOE E3407	SM9215D		
	Date Analyzed/			25-Mar-20/K	25-Mar-20/K		
Client I.D.	Sample I.D.	Date Collected				-	
70 Main St W	B20-08008-1	25-Mar-20	0	0	150		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Senior Microbiology Analyst

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.