

**C.O.C.: DW098202**

**REPORT No. B20-12003**

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 06-May-20

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 14-May-20

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

			Client I.D.		#1			
			Sample I.D.		B20-12003-1			
			Date Collected		06-May-20			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Chloroform	µg/L	1	EPA 8260	13-May-20/R	2			
Bromodichloromethane	µg/L	2	EPA 8260	13-May-20/R	< 2			
Dibromochloromethane	µg/L	2	EPA 8260	13-May-20/R	< 2			
Bromoform	µg/L	5	EPA 8260	13-May-20/R	< 5			
Total Trihalomethanes	µg/L	6	EPA 8260	13-May-20/R	< 6			



Richard Lecompte  
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \*

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.