

C.O.C.: DW098205

REPORT No. B20-12004

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 06-May-20

JOB/PROJECT NO.: Lyn Valley Mobile Home


DATE REPORTED: 14-May-20

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

			Client I.D.	#21			
			Sample I.D.	B20-12004-1			
			Date Collected	06-May-20			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	1	EPA 8260	13-May-20/R	< 1		
Bromodichloromethane	µg/L	2	EPA 8260	13-May-20/R	< 2		
Dibromochloromethane	µg/L	2	EPA 8260	13-May-20/R	4		
Bromoform	µg/L	5	EPA 8260	13-May-20/R	6		
Total Trihalomethanes	µg/L	6	EPA 8260	13-May-20/R	9		



Richard Lecompte
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.