

C.O.C.: DW108133

REPORT No. B20-22503

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 04-Aug-20

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 10-Aug-20

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

			Client I.D.	#1			
			Sample I.D.	B20-22503-1			
			Date Collected	04-Aug-20			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	1	EPA 8260	07-Aug-20/R	< 1		
Bromodichloromethane	µg/L	2	EPA 8260	07-Aug-20/R	< 2		
Dibromochloromethane	µg/L	2	EPA 8260	07-Aug-20/R	< 2		
Bromoform	µg/L	5	EPA 8260	07-Aug-20/R	< 5		
Total Trihalomethanes	µg/L	6	EPA 8260	07-Aug-20/R	< 6		



Richard Lecompte
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.