

C.O.C.: G55261

REPORT No. B20-31940

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 14-Oct-20

JOB/PROJECT NO.: Lyn Valley Mobile Park

DATE REPORTED: 21-Oct-20

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

Client I.D.	Lyn Valley Mobile Park-Effluent	Lyn Valley Mobile Park-Raw		
Sample I.D.	B20-31940-1	B20-31940-2		
Date Collected	14-Oct-20	14-Oct-20		

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
E coli	cfu/100mL	1	SM9222B	14-Oct-20/K	100000	9600000		
pH @25°C	pH Units		SM 4500H	16-Oct-20/O	7.87	7.33		
CBOD5	mg/L	3	SM 5210B	15-Oct-20/K	11	125		
Total Suspended Solids	mg/L	3	SM2540D	15-Oct-20/K	3	50		
Phosphorus-Total	mg/L	0.01	E3199A.1	16-Oct-20/K	0.94	7.57		
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	16-Oct-20/K	23.5	69.8		
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	19-Oct-20/K	1.74	64.9		
Ammonia (N)-unionized	mg/L	0.01	CALC	19-Oct-20/K	0.07	0.78		
Nitrite (N)	mg/L	0.1	SM4110C	19-Oct-20/O	0.4	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	19-Oct-20/O	3.1	< 0.1		



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.