

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW107924 REPORT No. B20-32977

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 21-Oct-20

DATE REPORTED: 23-Oct-20

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter Units		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	R.L.		1	1	10	
	Reference Meth	Reference Method Date Analyzed/Site		MOE E3407	SM9215D	
	Date Analyzed/S			21-Oct-20/K	21-Oct-20/K	
Client I.D.	Sample I.D.	Date Collected		•		
70 Main St. W	B20-32977-1	21-Oct-20	0	0	< 10	

E. Lumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology