

C.O.C.: G87723

REPORT No. B20-35698

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 11-Nov-20

JOB/PROJECT NO.: Lyn Valley Mobile Park

DATE REPORTED: 18-Nov-20

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

Client I.D.	Lyn Valley WW-Final Effluent	Lyn Valley WW-Raw		
Sample I.D.	B20-35698-1	B20-35698-2		
Date Collected	11-Nov-20	11-Nov-20		

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
E coli	cfu/100mL	1	SM9222B	11-Nov-20/K	40000	4500000		
pH @25°C	pH Units		SM 4500H	16-Nov-20/O	7.95	7.35		
CBOD5	mg/L	3	SM 5210B	12-Nov-20/K	< 3	160		
Total Suspended Solids	mg/L	3	SM2540D	13-Nov-20/K	9	60		
Phosphorus-Total	mg/L	0.01	E3199A.1	13-Nov-20/K	1.69	8.10		
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	13-Nov-20/K	6.8	66.3		
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	13-Nov-20/K	6.52	71.5		
Ammonia (N)-unionized	mg/L	0.01	CALC	13-Nov-20/K	0.31	0.90		
Nitrite (N)	mg/L	0.1	SM4110C	16-Nov-20/O	0.3	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	16-Nov-20/O	0.4	< 0.1		



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.