

C.O.C.: G55263

REPORT No. B20-37108

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 24-Nov-20

JOB/PROJECT NO.: HMR Monitoring Wells


DATE REPORTED: 03-Dec-20

P.O. NUMBER:

SAMPLE MATRIX: Groundwater

WATERWORKS NO.

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed	Client I.D.	Well #1	Well #2	Well #3	Well #4
					Sample I.D.	Date Collected			
Nitrite (N)	mg/L	0.1	SM4110C	27-Nov-20/O	B20-37108-1	< 0.1	< 0.1	< 0.1	< 0.1
Nitrate (N)	mg/L	0.1	SM4110C	27-Nov-20/O	B20-37108-2	1.6	1.5	0.3	0.8
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	30-Nov-20/K	B20-37108-3	1.2	0.3	0.2	0.1
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	26-Nov-20/K	B20-37108-4	0.02	0.01	< 0.01	< 0.01



Richard Lecompte
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.