

C.O.C.: G87724

REPORT No. B20-38591

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 08-Dec-20

JOB/PROJECT NO.: Lyn Valley Mobile Park

DATE REPORTED: 15-Dec-20

P.O. NUMBER:

SAMPLE MATRIX: Waste Water

WATERWORKS NO.

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed	Client I.D.	Final Effluent	WW-Raw		
					Sample I.D.				
E coli	cfu/100mL	1	SM9222B	08-Dec-20/K		270000	2300000		
CBOD5	mg/L	3	SM 5210B	09-Dec-20/K	B20-38591-1	< 3	62	B20-38591-2	
Total Suspended Solids	mg/L	3	SM2540D	10-Dec-20/K		< 3	15		
Phosphorus-Total	mg/L	0.01	E3199A.1	09-Dec-20/K		0.29	3.22		
Total Kjeldahl Nitrogen	mg/L	0.1	E3199A.1	09-Dec-20/K		1.3	29.7		
Ammonia (N)-Total	mg/L	0.01	SM4500-NH3-H	10-Dec-20/K		0.95	25.7		
Ammonia (N)-unionized	mg/L	0.01	CALC	10-Dec-20/K		0.03	0.35		
Nitrite (N)	mg/L	0.1	SM4110C	10-Dec-20/O		0.4	< 0.1		
Nitrate (N)	mg/L	0.1	SM4110C	10-Dec-20/O		0.5	< 0.1		



Michelle Dubien
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.