

## CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW107932 **REPORT No. B20-39391** 

**Report To:** 

**Property Management Inc** 323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

DATE RECEIVED: 15-Dec-20

DATE REPORTED: 17-Dec-20 SAMPLE MATRIX: Drinking Water **Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Lyn Valley Mobile Home

P.O. NUMBER:

WATERWORKS NO. 260023465

	Parameter	Parameter		E coli	Heterotrophic Plate Count		
	Units R.L. Reference Method Date Analyzed/Site		cfu/100mL	cfu/100mL	cfu/mL		
			1	1	10		
			MOE E3407	MOE E3407	SM9215D		
			15-Dec-20/K	15-Dec-20/K	15-Dec-20/K		
Client I.D.	Sample I.D.	Date Collected				•	
70 Main St W	B20-39391-1	15-Dec-20	0	0	30		
Pumphouse-Raw	B20-39391-2	15-Dec-20	0	0			

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill, B-Barrie

Evan Livermore Supervisor/Microbiology