

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW104758

REPORT No. B21-01151

Report To:	Caduceon Environmental Laboratories				
Property Management Inc	285 Dalton Ave				
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1				
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001				
Attention: Isaac Berman	Fax: 613-544-2770				
DATE RECEIVED: 12-Jan-21	JOB/PROJECT NO.: HMR Estates Pump House				
DATE REPORTED: 15-Jan-21	P.O. NUMBER:				
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768				

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units	Units R.L. Reference Method		cfu/100mL	cfu/mL	
	R.L.			1	10	
	Reference Meth			MOE E3407	SM9215D	
	Date Analyzed/S	Date Analyzed/Site		13-Jan-21/K	13-Jan-21/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B21-01151-1	12-Jan-21	0	0	< 10	
Pumphouse-Raw	B21-01151-2	12-Jan-21	0	0		

E. Sumore

R.L. = Reporting Limit Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie Evan Livermore Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.