

## **CERTIFICATE OF ANALYSIS**

Final Report-Microbiology

C.O.C.: DW113493 REPORT No. B21-26265

Report To:

**2825612ONT Inc.** 227 Big Hill Rd.,

Seeley's Bay ON K0H 2N0 Canada

Attention: Manipal Sagoo

DATE RECEIVED: 18-Aug-21

DATE REPORTED: 20-Aug-21

SAMPLE MATRIX: Drinking Water

**Caduceon Environmental Laboratories** 

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: Big Hill

P.O. NUMBER:

WATERWORKS NO. 260019604

	Parameter  Units R.L. Reference Method		Total Coliform	E coli		
			cfu/100mL	cfu/100mL		
			1	1		
			MOE E3407	MOE E3407		
	Date Analyzed/Site		18-Aug-21/K	18-Aug-21/K		
Client I.D.	Sample I.D.	Date Collected			•	
#6	B21-26265-1	18-Aug-21	0	0		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology