

C.O.C.: DW113490

REPORT No. B21-26267

Report To:

Property Management Inc
 323 Dundas Street East, Unit 3,
 Trenton Ont K8V 5W5 Canada

Attention: Isaac Berman

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 18-Aug-21

JOB/PROJECT NO.: Lyn Valley Mobile Home

DATE REPORTED: 23-Aug-21

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260023465

			Client I.D.	#21			
			Sample I.D.	B21-26267-1			
			Date Collected	18-Aug-21			
Parameter	Units	R.L.	Reference Method	Date/Site Analyzed			
Chloroform	µg/L	1	EPA 8260	20-Aug-21/R	< 1		
Bromodichloromethane	µg/L	2	EPA 8260	20-Aug-21/R	< 2		
Dibromochloromethane	µg/L	2	EPA 8260	20-Aug-21/R	3		
Bromoform	µg/L	5	EPA 8260	20-Aug-21/R	< 5		
Total Trihalomethanes	µg/L	6	EPA 8260	20-Aug-21/R	< 6		



Richard Lecompte
 Laboratory Supervisor

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from